DART AEROSPACE LTD	Work Order :	Disassemble	
		19177	
Description: Dsassemble 140003			
	Approval :	SALES. pol Jb.	
		Page 1 of 1	

\*

1	PK	Remove from Stock					
		Qty Part Number L K10003	Description Soddle Kit	Batch B18812	a	03.05.21	1
2	PK	Return to Stock					
		Qty Part Number  29	Description  Mut. Washer Washer Washer Washer Soft Bott Bott Bushing Saddle spacer Set Acrew Lug Assembly Lus	Batch  MIIISI  MIJUSS  MIJUSS		03.05.21	
		Ccox ED -3/05	/22 Suc	LEVEL O	W	03.05.22	-

Rev	Date	Change	Revised by	Approved